

# Cumbria Countryside Access

## UCR and BOAT Survey Form

UCR Number and/or BOAT Number	1054	OS Map	86	
Total length	1.3	Grid References	From	580 637
Length unsurfaced	0.62		To	580 624
		Location	Denton Hall	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	<b>X</b>
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S. Pighills	Organization	Cumbria TRF
Date	08/08/08	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	100%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Farm track from North to Denton Hall premises

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other  
Route is blocked with garden and fence at Denton Hall then continues South to A69 but is completely blocked at railway line, where it has been replaced with stiles.

General description of route, and observations  Good route to Denton Hall from North, good route from A69 to Railway but middle section effectively closed.  <b>Question:</b> it appears Denton Hall access from A69 was substituted by tarmac road (marked yellow on Definitive Map) along FP alignment Presume this now a legitimate route for MPV followers of U1054?	Signed from main highway	Yes
	Signed both ends	No
	Access from main Highway - easy	Yes
	Route - through	Yes?
	- dead end	
	Fords or water crossings	
	Gradient - generally flat	
	- generally undulating	Yes
- has steep hills		

Should normally be passable by	2 wheel drive	Yes	Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	14ft		

Recommend one way use due to steepness, narrowness, other condition, state reason

4 wheels	
2 wheels	

Worth evaluating for Trumper use? ( motorized scooters for the disabled with off road capability)

Looks practical	Yes	Maybe	
No			