

# Cumbria Countryside Access

## UCR and BOAT Survey Form

UCR Number and/or BOAT Number	U3222	OS Map	91	
Total length	0.31	Grid References	From	735 206
Length unsurfaced	0.31		To	733 204
		Location	Hilton	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	<b>X</b>
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	Ian Knowles	Organization or interest	TRF
Date	01/09/07		

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	100%
	Crushed stone		Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Good

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other Don't go through farmyard, exit is 20ft up beyond barn

General description of route, and observations  Very short route behind barns	Signed from main highway		No
	Signed both ends		
	Access from main Highway	- easy - awkward	Yes
	Route	- through - dead end	Yes
	Fords or water crossings		
	Gradient	- generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive	No	Quad	Yes
	4 wheel drive	No	Trail bike	Yes
	Carriage	No		
	Approx. width at narrowest	12ft		

Recommend one way use due to steepness, narrowness, other condition, state reason		4 wheels	
		2 wheels	

Worth evaluating for Trampler use? ( motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe	
	No			