

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5077	OS Map	96	
Total length	1.2	Grid References	From	269 864
Length unsurfaced	1		To	275 851
		Location	Gawthwaite	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	Yes
	Route with little or no use not likely to require monitoring/ management	
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S.Stout	Organization or interest	TRF
Date	14/04/21		

Surface (note % of each type of surface, Describe "other")	Tarmac	40%	Grass	10%
	Crushed stone	30%	Mud	
	Rocky	20%	Other	

Condition of surface (rutted, washed out, etc.) Hill section repaired Dec 2020

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)	Good condition from Gawthwaite to last field, then some rutting Surface repairs completed 2020 on northern end. Surface now good and drainage generally working Surrounding hillsides are SSSI designation, stay on the trail only Drystone walls are falling down in fields.
---	--

Considerations for use and sensitivity re ecological issues, farming issues, other	Farmers at both ends are concerned, be polite and stay on marked trails. Cattle and sheep all around, be aware and travel steadily. You will encounter horse riders and cyclists Surrounding hillsides SSSI
--	--

General description of route, and observations Tarmac generally deteriorating from Gawthwaite, then grass Field section before descending through moorland to regain road Some gates	Signed from main highway	Yes
	Signed both ends	
	Access from main Highway - easy	Yes
	Route - through	Yes
	- dead end	
	Fords or water crossings	No
	Gradient - generally flat - generally undulating - has steep hills	Yes

Should normally be passable by *Last gate is at an awkward angle, effectively 6ft 4in	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	7ft 6in		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	No
	2 wheels	No

Worth evaluating for Trampler use? (motorized scooters for the disabled with off road capability)	Looks practical	Maybe	Yes
	No		