

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5079	OS Map	96	
Total length	1.14	Grid References	From	277 871
Length unsurfaced	1.14		To	272 865
		Location	Raisthwaite Lane	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	Yes
	Route with little or no use not likely to require monitoring/ management	
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	R. France	Organization	TRF
Date	01/07/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	75%
	Crushed stone	25%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Grassy, some mud

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) Take care not to cut up in wet conditions

Considerations for use and sensitivity re ecological issues, farming issues, other Take care of stock

General description of route, and observations Off moor from western end, through gate to a very narrow part hedged section impractical for a 4x4. Farmland alongside is easily damaged and must not be used. Through farm buildings onto track out to east.	Signed from main highway	No	
	Signed both ends		
	Access from main Highway	- easy - awkward	Yes
	Route	- through - dead end	Yes
	Fords or water crossings		No
	Gradient	- generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive		Quad	No
	4 wheel drive	No	Trail bike	Yes
	Carriage	No		
	Approx. width at narrowest	4 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	No

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical		Maybe
	No	No	