

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5050	OS Map	96	
Total length	2.53	Grid References	From	336 944
Length unsurfaced	2.53		To	357 955
		Location	Grisedale	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	X
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S. Pighills	Organization	TRF	
Date	08/09/07	or interest		

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	50%	Mud	
	Rocky	50%	Other	

Condition of surface (rutted, washed out, etc.)	Loose stone and rock at either end
---	------------------------------------

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)	Eastern section subject to water damage
---	---

Considerations for use and sensitivity re ecological issues, farming issues, other	Popular walking and cycling route, particularly Western end from Visitor Centre Take particular care in this area
--	--

General description of route, and observations Generally stoney route through Forest	Signed from main highway	Yes	
	Signed both ends	Yes	
	Access from main Highway	- easy - awkward	Yes
	Route	- through - dead end	Yes
	Fords or water crossings		
	Gradient	- generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage			
	Approx. width at narrowest	10 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	LDNPA Code says 4X4s use West to East only	4 wheels	Yes
		2 wheels	No

Worth evaluating for Trumper use? (motorized scooters for the disabled with off road capability)	Looks practical		Maybe	Yes
	No			