

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or	5351	OS Map	97	
BOAT Number	556011	Grid References	From	493 815
Total length	0.6		To	497 818
Length unsurfaced	0.6	Location	Milnthorpe	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	J. S. Pighills	Organization	TRF	
Date	23/08/07	or interest		

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	100%
	Crushed stone		Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Underlying hard surface with grass on top

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations ***** Incorrectly signed Bridleway, sign broken at eastern end Grassy lane between hedges, potential to be overgrown 4x4 use would impact on fallen banks	Signed from main highway	*****
	Signed both ends	*****
	Access from main - easy	Yes
	Highway - awkward	
	Route - through	Yes
	- dead end	
	Fords or water crossings	
Gradient - generally flat		
- generally undulating	Yes	
- has steep hills		

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	No		
	Approx. width at narrowest	8 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Trumper use? (motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe	
	No			