

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5378	OS Map	97	
Total length	0.7	Grid References	From	619 857
Length unsurfaced	0.6		To	619 850
		Location	Hawkin Hall	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	J. S. Pighills	Organization or interest	TRF
Date	23/08/07		

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	50%
	Crushed stone	50%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Tractor ruts in grass section

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations Hedged lane, mainly farm field access, potential to be overgrown at southern end	Signed from main highway	Yes
	Signed both ends	Yes
	Access from main Highway	- easy - awkward
	Route	- through - dead end
	Fords or water crossings	
	Gradient	- generally flat - generally undulating - has steep hills
		Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	10 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason

4 wheels	
2 wheels	

Worth evaluating for Trumper use? (motorized scooters for the disabled with off road capability)

Looks practical		Maybe	Yes
No			