Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or	1142	OS Map	85	
BOAT Number		Grid References	From	377 589
Total length	4.77		To	378 459
Length unsurfaced	2.28	Location	Gaitsgill	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/managment	
	Route with moderate use requiring some monitoring/managment	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends	

Surveyor	G. Wilson	Organization or interest	LARA
Date	05/10/07		

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	100%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.)	Somewhat rutted with grass centre

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)	Will develop deep puddles in wet weather

Considerations for use and sensitivity re ecological issues, farming issues, other	None

General description of route, and observations	Signed from main highway	Yes
	Signed both ends	Yes
Hedged farm type lane. Used by tractors.	Access from main - easy	Yes
	Highway - awkward	
Western section is Signed Public Way at both ends, with Bridleway on same sign. Route is not Bridleway	Route - through	Yes
North/Eastern section signed Public Way	- dead end	
	Fords or water crossings	
	Gradient - generally flat	Yes
	- generally undulating	
	- has steep hills	

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest		12 ft	

Recommend one way use due to steepness, narrowness, other condition, state reason		4 wheels	
		2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical		Maybe	Yes
	No			