Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or	1158	OS Map	85	
BOAT Number		Grid References	From	418 483
Total length	1.375		To	431 483
Length unsurfaced	1.3	Location	Foulbridge	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/managment	
	Route with moderate use requiring some monitoring/managment	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	
LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends		

Surveyor	G. Wilson	Organization or interest	LARA
Date	05/10/07		

Surface (note % of each type of surface, Describe "other")	Tarmac	15%	Grass	
	Crushed stone	85%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.)	Good surface with some puddles

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)	None

Considerations for use and sensitivity re ecological issues, farming issues, other	None

General description of route, and observations

Wide, hedged lane, crossing M6

Signed from main highway		No
Signed both ends		
Access from main Highway	- easy	Yes
	- awkward	
Route	- through	Yes
	- dead end	
Fords or water crossings		
Gradient	- generally flat	Yes
	- generally undulating	
	- has steep hills	

Should normally be passable by	2 wheel drive	Yes	Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest		12 ft	

Recommend one way use due to steepness, narrowness, other condition, state reason		4 wheels	
		2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe	
	No			