

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	U2080	OS Map	85	
Total length	1.5	Grid References	From	179419
Length unsurfaced	1.5		To	190420
		Location	Baggrow	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	David Young	Organization or interest	NL 4x4
Date	16/12/07		

Surface (note % of each type of surface, Describe "other")	Tarmac	5%	Grass	
	Crushed stone	95%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Standing water in places – not deep

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other Used by walkers

General description of route, and observations Stone/gravel route, narrow in places with overgrown hedges. Awkward for horses or walkers to pass by 4x4s	Signed from main highway	No
	Signed both ends	
	Access from main Highway - easy - awkward	Yes
	Route - through - dead end	Yes
	Fords or water crossings	
	Gradient - generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive	Yes	Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	10 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason

4 wheels	
2 wheels	

Worth evaluating for Trampler use? (motorized scooters for the disabled with off road capability)

Looks practical	Yes	Maybe	
No			