

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	1213	OS Map	86	
Total length	3.2	Grid References	From	547 528
Length unsurfaced	1.5		To	547 522
		Location	Albyfield	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S. Pighills	Organization	Cumbria TRF
Date	08/08/08	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac	30%	Grass	60^%
	Crushed stone		Mud	
	Rocky		Farmyard	10%

Condition of surface (rutted, washed out, etc.) OK

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) N/A

Considerations for use and sensitivity re ecological issues, farming issues, other Passes through Albyfield farmyard – gates etc.

General description of route, and observations Gate difficult at Albyfield Farm, grass north of farm, tarmac south Only signposted at northern end	Signed from main highway	Yes	
	Signed both ends		
	Access from main Highway	- easy - awkward	Yes
	Route	- through - dead end	Yes
	Fords or water crossings		
	Gradient	- generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive	No	Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	12 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason

4 wheels	
2 wheels	

Worth evaluating for Trumper use? (motorized scooters for the disabled with off road capability)

Looks practical	Yes	Maybe
No		