

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	3051	OS Map	86	
Total length	1.59	Grid References	From	518 459
Length unsurfaced	1.55		To	519 448
		Location	Longdales	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	Geoff Wilson	Organization	ARA / TRF	
Date	17/10/07	or interest		

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	10%
	Crushed stone	90%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Good

Apparent sensitivity to winter/weather conditions
(river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re
ecological issues, farming issues, other None

General description of route, and observations Wide, well surfaced hedged lane	Signed from main highway	No	
	Signed both ends		
	Access from main Highway	- easy - awkward	Yes
	Route	- through - dead end	Yes
	Fords or water crossings		
	Gradient	- generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	15 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Trumper use? (motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe
	No		