

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	3107	OS Map	86	
Total length	0.84	Grid References	From	723 463
Length unsurfaced	0.67		To	728 457
		Location	Alston	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	Dave Willetts	Organization	TRF
Date	14/10/07	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	100%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Good, flat and smooth

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations Wide, newly laid surface	Signed from main highway	Yes
	Signed both ends	No
	Access from main Highway	Yes
	- easy	
	- awkward	
	Route	Yes
	- through	
- dead end		
Fords or water crossings		
Gradient	Yes	
- generally flat		
- generally undulating		
- has steep hills		

Should normally be passable by	2 wheel drive	Yes	Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	20 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Trumper use? (motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe	
	No			