

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	3111	OS Map	86	
Total length	2.86	Grid References	From	758 483
Length unsurfaced	1.02		To	755 473
		Location	Nenthall	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	Dave Willetts	Organization or interest	TRF
Date	14/10/07		

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	100%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Hard, well compacted surface

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations From map ref. 755 473, a gated route, hard surfaced between stone walls, signed "By Road" Becomes Footpath Only at county border, map ref. 758 483	Signed from main highway	Yes
	Signed both ends	
	Access from main Highway - easy - awkward	Yes
	Route - through - dead end	No X
	Fords or water crossings	
	Gradient - generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive	Yes	Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	12 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason

4 wheels	
2 wheels	

Worth evaluating for Trumper use? (motorized scooters for the disabled with off road capability)

Looks practical	Yes	Maybe	
No			