

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	U3471 02	OS Map	86	
Total length	1.2	Grid References	From	592 412
Length unsurfaced	1.2		To	599 403
		Location	Viol Moor	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	Geoff Wilson	Organization or interest	LARA / TRF
Date	17/09/07		

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	90%
	Crushed stone		Mud	10%
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Some ruts

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations Grassy lane between walls * Signed "Footpath" at Gamblesby village end	Signed from main highway	*
	Signed both ends	
	Access from main Highway	Yes
	Route	Yes
	Fords or water crossings	
	Gradient	Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	No	Trail bike	Yes
	Carriage	None		
	Approx. width at narrowest	8 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Trumper use? (motorized scooters for the disabled with off road capability)	Looks practical		Maybe
	No	No	