

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or		OS Map	90	
BOAT Number	361002	Grid References	From	468 106
Total length	1.5		To	474 092
Length unsurfaced	1.5	Location	Gatesgarth north side	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/managment	Yes
	Route with moderate use requiring some monitoring/managment	
	Route with little or no use not likely to require monitoring/ management	
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S. Pighills	Organization	TRF
Date	04/08/07	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	100%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Unremittingly steep and rocky route

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) Generally unaffected by weather

Take great care on loose and rocky hairpin bends. Drive/ride to minimize any surface damage

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations LDNPA TRO = once a month permit use only, apply LDNPA 4x4 must be short wheelbase and not softroader 2 gates	Signed from main highway	Yes
	Signed both ends	
	Access from main Highway - easy	Yes
	- awkward	
	Route - through	Yes
	- dead end	
	Fords or water crossings	No
Gradient - generally flat		
- generally undulating		
- has steep hills	Yes	

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage			
	Approx. width at narrowest	10 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	Yes
	2 wheels	No

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical	Maybe	Yes
	No		