

Cumbria Countryside Access

UCR and BOAT Survey Form

| | | | | |
|-------------------|----------------|-----------------|---------|---------|
| UCR Number and/or | 3173 | OS Map | 90 | |
| BOAT Number | Part is 361001 | Grid References | From | 543 169 |
| Total length | 1.93 | | To | 557 178 |
| Length unsurfaced | 1.93 | Location | Rosgill | |

| | | |
|---|--|-----|
| CCC Classification (Tick recommendation) | Route with significant use requiring significant monitoring/management | |
| | Route with moderate use requiring some monitoring/management | |
| | Route with little or no use not likely to require monitoring/ management | Yes |
| | Unsuitable route, should not be on MPV sustainable access map | |

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

| | | | | |
|----------|-------------|--------------|-----|--|
| Surveyor | S. Pighills | Organization | TRF | |
| Date | 04/08/07 | or interest | | |

| | | | | |
|---|---------------|-----|-------|--|
| Surface (note % of each type of surface, Describe "other") | Tarmac | | Grass | |
| | Crushed stone | Yes | Mud | |
| | Rocky | | Other | |

Condition of surface (rutted, washed out, etc.) Generally good, with some puddles

Apparent sensitivity to winter/weather conditions
(river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re
ecological issues, farming issues, other None

| | | |
|--|---------------------------------|-----|
| General description of route, and observations Walled farm type lane, passing through quarry property and railway spur at one point Some gates | Signed from main highway | Yes |
| | Signed both ends | Yes |
| | Access from main Highway - easy | Yes |
| | - awkward | |
| | Route - through | Yes |
| | - dead end | |
| | Fords or water crossings | No |
| Gradient - generally flat | Yes | |
| | - generally undulating | |
| | - has steep hills | |

| | | | | |
|--------------------------------|----------------------------|-------|------------|-----|
| Should normally be passable by | 2 wheel drive | | Quad | Yes |
| | 4 wheel drive | Yes | Trail bike | Yes |
| | Carriage | Yes | | |
| | Approx. width at narrowest | 12 ft | | |

| | | |
|--|----------|----|
| Recommend one way use due to steepness, narrowness, other condition, state reason | 4 wheels | No |
| | 2 wheels | No |

| | | | |
|--|-----------------|-----|-------|
| Worth evaluating for Trumper use? (motorized scooters for the disabled with off road capability) | Looks practical | Yes | Maybe |
| | No | | |