

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or	U3278	OS Map	90 & 91	
BOAT Number	355003	Grid References	From	NY585 047
Total length	3		To	NY551 036
Length unsurfaced	2.49	Location	Breasthigh	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	X
	Route with little or no use not likely to require monitoring/ management	
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification when applicable, criteria as above, but green becomes light green for dead ends

Surveyor	P. de Borde	Organization or interest	GLASS, Cumbria Countryside Access
Date	11/10/2009		

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	40%	Mud	
	Rocky	60%	Other	

Condition of surface (rutted, washed out, etc.) Severe water erosion on Eastern side

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)

Potential to wash out on both Western & Eastern sides

River crossing on western side can be very deep, fast flowing & sometimes impassable during & after wet weather

Considerations for use and sensitivity re ecological issues, farming issues, other

Route passes through farming Access Land

General description of route, and observations The eastern side has suffered from major water erosion damage in Aug/Sept 2009 downhill from the culvert at NY5692 0463. There are several 3-4ft deep, steep sided holes in the surface & large quantities of the track structure has been washed away. The route is now impassable to 4x4's & carriages. "Breast High, U3278, is subject to a Temporary Traffic Restriction Order"	Signed from main highway	Yes
	Signed both ends	Yes
	Access from main Highway - easy	Yes (east)
	- awkward	Yes (west)
	Route - through	Yes
	- dead end	
	Fords or water crossings	Yes
	Gradient - generally flat	
- generally undulating		
- has steep hills	Yes	

Should normally be passable by	2 wheel drive	No	Quad	
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	?		
	Approx. width at narrowest	7ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	No
	2 wheels	No

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical		Maybe	
	No	*		