

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5001	OS Map	90
Total length	2.46	Grid References	From 300 031
Length unsurfaced	2.46	To	308 014
		Location	Tilberthwaite

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	Yes
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S.Pighills	Organization or interest	Countryside Access
Date	10/09/08		

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	50%	Mud	
	Rocky	50%	Other	

Condition of surface (rutted, washed out, etc.) Hardcore track with rocky outcrops

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)

Seasonal Restraint: 4x4 users requested not to use this route Jan-Feb 2011 due to snow and ice damage; motorcyclists should take great care. Advisory signage at location

Considerations for use and sensitivity re ecological issues, farming issues, other

Take care for walkers etc. especially at weekends and holidays

General description of route, and observations Generally very rocky track with stone outcrops, through moorland Some gates	Signed from main highway	No
	Signed both ends	
	Access from main Highway	Yes
	Route	Yes
	Fords or water crossings	No
	Gradient	Yes
		Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	No		
	Approx. width at narrowest	10 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	Yes
	2 wheels	No

Worth evaluating for Trumper use? (motorized scooters for the disabled with off road capability)	Looks practical	Maybe	Yes
	No		

