

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or	5739	OS Map	90	
BOAT Number	543044	Grid References	From	311 062
Total length	1.85		To	296 064
Length unsurfaced	1.69	Location	Langdale	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	X
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	J.S.Pighills	Organization	TRF	
Date	27/08/07	or interest		

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	Yes	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.)	Good, some puddles
---	--------------------

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)	None
--	------

Considerations for use and sensitivity re ecological issues, farming issues, other	Care needed – well used by walkers and cyclists
---	---

General description of route, and observations Broad, hedged and walled track, relatively smooth	Signed from main highway	Yes
	Signed both ends	Yes
	Access from main Highway - easy	Yes
	Route - awkward	
	Route - through	Yes
	Route - dead end	
	Fords or water crossings	
Gradient - generally flat - generally undulating - has steep hills	Yes	

Should normally be passable by	2 wheel drive	Yes	Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	14 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Trumper use? (motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe	
	No			