

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5004	OS Map	90	
Total length	1.45	Grid References	From	323 019
Length unsurfaced	0.58		To	318 019
		Location	Oxen Fell	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	Yes
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends Yes

Surveyor	S. Pighills	Organization	TRF	
Date	31/07/07	or interest		

Surface (note % of each type of surface, Describe "other")	Tarmac	60%	Grass	
	Crushed stone	35%	Mud	
	Rocky	5%	Other	

Condition of surface (rutted, washed out, etc.)	Unsurfaced part rough crushed stone with rocky outcrops
---	---

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)	None
---	------

Considerations for use and sensitivity re ecological issues, farming issues, other	Care through farm at end of tarmac Take care – high numbers of walkers etc. at weekends and holidays
--	---

General description of route, and observations Twisty and rocky track through woodland, several gates	Signed from main highway	No
	Signed both ends	
	Access from main Highway - easy	Yes
	Route - awkward	
	Route - through	Yes
	Route - dead end	
	Fords or water crossings	No
Gradient - generally flat - generally undulating - has steep hills		Yes
		Yes
		Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	?		
	Approx. width at narrowest			

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	No
	2 wheels	No

Worth evaluating for Trumper use? (motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe	
	No			