

# Cumbria Countryside Access

## UCR and BOAT Survey Form

UCR Number and/or	U3250	OS Map	91	
BOAT Number	319004	Grid References	From	629 139
Total length	2.59		To	636 130
Length unsurfaced	1.28	Location	S of Crosby Ravensworth	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	Yes
	Route with little or no use not likely to require monitoring/ management	
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S. Pighills	Organization	TRF
Date	04/08/07	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	100%
	Crushed stone		Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.)      Good, almost unbroken

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)      None

Considerations for use and sensitivity re ecological issues, farming issues, other      Take care for stock

General description of route, and observations  Open crossing of unfenced pasture	Signed from main highway	Yes
	Signed both ends	
	Access from main Highway - easy - awkward	Yes
	Route - through - dead end	Yes
	Fords or water crossings	
	Gradient - generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest			

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Trumper use? ( motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe	
	No			