

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or	U3277/02	OS Map	91	
BOAT Number	355004	Grid References	From	587 050
Total length	1.46		To	575 049
Length unsurfaced	1.21	Location	Bretherdale Head	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S. Pighills + Group	Organization	up, Cumbria Countryside
Date	17/08/09	or interest	Access

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	70%
	Crushed stone		Mud	
	Rocky	30%	Other	

Condition of surface (rutted, washed out, etc.) Small area washed out

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) Very slippery river crossing

Considerations for use and sensitivity re ecological issues, farming issues, other Take care for stock

General description of route, and observations Very narrow and stony from river crossing, then open field edge, gated	Signed from main highway	Yes	
	Signed both ends		
	Access from main Highway	- easy - awkward	Yes
	Route	- through - dead end	Yes
	Fords or water crossings		Yes
	Gradient	- generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive		Quad	No
	4 wheel drive	No	Trail bike	Yes
	Carriage			
	Approx. width at narrowest	4 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason		4 wheels	
		2 wheels	

Worth evaluating for Trampler use? (motorized scooters for the disabled with off road capability)	Looks practical		Maybe
	No	*	