

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	2187	OS Map	89	
Total length	0.52	Grid References	From	053 299
Length unsurfaced	0.52		To	055 294
		Location	Great Clifton	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	
	Unsuitable route, should not be on MPV sustainable access map	X

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	F. Quayle	Organization	NL 4x4
Date	15/09/07	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac	50%	Grass	
	Crushed stone	50%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Some ruts

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations Flat single carriageway Locked gate half way down route	Signed from main highway	No
	Signed both ends	
	Access from main Highway	Yes
	Route	
	- easy - awkward	
	- through - dead end	X
	Fords or water crossings	
Gradient - generally flat - generally undulating - has steep hills	Yes	

Should normally be passable by	2 wheel drive	Yes	Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest			

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Trumper use? (motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe	
	No			