

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5502	OS Map	98	
Total length	3.21	Grid References	From	713 979
Length unsurfaced	2.42		To	695 955
		Location	Bluecaster Side	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/managment	
	Route with moderate use requiring some monitoring/managment	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	Ian Knowles	Organization	TRF
Date	30/09/07	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	90%
	Crushed stone		Mud	5%
	Rocky	5%	Other	

Condition of surface (rutted, washed out, etc.) Good

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) Consideration for surface in wet weather

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations Gate at each end, grassy old road with a few boggy sections crossing open moorland	Signed from main highway	No
	Signed both ends	
	Access from main Highway - easy	Yes
	Route - through - dead end	Yes
	Fords or water crossings	
	Gradient - generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	No	Trail bike	Yes
	Carriage			
	Approx. width at narrowest	6 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical	Maybe	Yes
	No		