

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5073	OS Map	96	
Total length	0.12	Grid References	From	222 866
Length unsurfaced	0.12		To	223 865
		Location	Broughton	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	Yes
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S. Pighills	Organization	TRF
Date	16/07/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	100%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Rough

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations Steep hedged lane forming short cut off Broughton road	Signed from main highway	No
	Signed both ends	
	Access from main Highway - easy	Yes
	Route - through - dead end	Yes
	Fords or water crossings	No
	Gradient - generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	No		
	Approx. width at narrowest	12 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	No
	2 wheels	No

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical		Maybe
	No	No	