

# Cumbria Countryside Access

## UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5230	OS Map	96	
Total length	1	Grid References	From	407 808
Length unsurfaced	0.8		To	413 802
		Location	Lindale	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/management	<b>X</b>
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	R & S France	Organization	TRF
Date	27/05/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	90%
	Crushed stone	5%	Mud	5%
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Good until recently washed out in parts

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) Liable to surface damage by heavy rain/flooding

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations  Grassy track between walls and hedges, somewhat overgrown	Signed from main highway	No
	Signed both ends	No
	Access from main Highway	Yes
	Route	Yes
	Fords or water crossings	
	Gradient	Yes

Should normally be passable by	2 wheel drive	No	Quad	Yes
	4 wheel drive	No	Trail bike	Yes
	Carriage	No		
	Approx. width at narrowest	5ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Trumper use? ( motorized scooters for the disabled with off road capability)	Looks practical		Maybe	Yes
	No			