

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5050	OS Map	96	
Total length	2.53	Grid References	From	336 944
Length unsurfaced	2.53		To	357 955
		Location	Grisedale	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	X
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	R & S France	Organization	TRF
Date	28/07/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	50%	Mud	
	Rocky	50%	Other	

Condition of surface (rutted, washed out, etc.) Loose stone and rock at either end

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) Eastern section subject to water damage

Considerations for use and sensitivity re ecological issues, farming issues, other Popular walking and cycling route, particularly Western end from Visitor Centre
Take particular care in this area

General description of route, and observations Generally stoney route through Forest	Signed from main highway	Yes	
	Signed both ends	Yes	
	Access from main Highway	- easy - awkward	Yes
	Route	- through - dead end	Yes
	Fords or water crossings		
	Gradient	- generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage			
	Approx. width at narrowest	10 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	LDNPA Code says from	4 wheels	Yes
	East only	2 wheels	No

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical	Maybe	Yes
	No		