

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5246	OS Map	96	
Total length	0.3	Grid References	From	420 878
Length unsurfaced	0.3		To	418 878
		Location	Swallowmire	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	R & S France	Organization	TRF
Date	27/05/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac	10%	Grass	
	Crushed stone	90%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) After farmyard, well surfaced lane through woodland

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re ecological issues, farming issues, other Goes uphill right through farmyard, care & courtesy needed

General description of route, and observations Uphill off minor road close through farmyard, then winds through wood. No sign at W end	Signed from main highway	Yes
	Signed both ends	No
	Access from main Highway - easy	Yes
	Route - through - dead end	Yes
	Fords or water crossings	
	Gradient - generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	8ft at gate		

Recommend one way use due to steepness, narrowness, other condition, state reason

4 wheels	
2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)

Looks practical		Maybe
No	No	