

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5609	OS Map	96	
Total length	0.38	Grid References	From	427 841
Length unsurfaced	0.38		To	425 844
		Location	Witherslack	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	R & S France	Organization	TRF
Date	01/07/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	100%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Good

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) Puddles

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations Straight gravel road with wall at both sides	Signed from main highway	No
	Signed both ends	
	Access from main Highway	Yes
	Route	Yes
	Fords or water crossings	
	Gradient - generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive	Yes	Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	12ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Trampler use? (motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe	
	No			