

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or	5597	OS Map	97	
BOAT Number	577015	Grid References	From	470 919
Total length	0.32		To	471 922
Length unsurfaced	0.32	Location	Underbarrow	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	X
	Route with little or no use not likely to require monitoring/ management	
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	R & S France	Organization	TRF
Date	30/04/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	30%
	Crushed stone	50%	Mud	20%
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Hard surface under rutted grass

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) Deep puddles in wet weather due to absence of drains

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations Tractor rutted grass and stone lane between hedges	Signed from main highway	Yes
	Signed both ends	Yes
	Access from main - easy	Yes
	Highway - awkward	
	Route - through	Yes
	- dead end	
	Fords or water crossings	
	Gradient - generally flat	Yes
- generally undulating		
- has steep hills		

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	14 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical		Maybe
	No	No	