

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5432	OS Map	97	
Total length	0.85	Grid References	From	503 785
Length unsurfaced	0.85		To	508 779
		Location	Hale	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	R & S France	Organization	TRF
Date	29/04/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	100%
	Crushed stone		Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Slightly worn in centre by horses

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) Boggy in wet weather

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations Hedged lane leading to houses at northern end Rather overgrown in summer Tight bend at northern end has very little (2") clearance	Signed from main highway	No
	Signed both ends	
	Access from main Highway - easy	Yes
	Highway - awkward	
	Route - through	Yes
	- dead end	
	Fords or water crossings	
Gradient - generally flat	Yes	
- generally undulating		
- has steep hills		

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	7 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe
	No		