

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or	5372	OS Map	97	
BOAT Number	Part is 552014	Grid References	From	554 812
Total length	1		To	547 808
Length unsurfaced	0.75	Location	Lupton	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/managment	
	Route with moderate use requiring some monitoring/managment	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	R & S France	Organization	TRF
Date	29/04/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	100%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.)

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)	Ford could be deep/dangerous in wet weather
--	---

Considerations for use and sensitivity re ecological issues, farming issues, other	None (Passes through business property at northern end)
---	--

General description of route, and observations Metalled track, partly hedged, one gate North end onto A65	Signed from main highway	No
	Signed both ends	
	Access from main - easy	Yes
	Highway - awkward	
	Route - through	Yes
	- dead end	
	Fords or water crossings	Yes
Gradient - generally flat		
- generally undulating	Yes	
- has steep hills		

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	12 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical		Maybe	Yes
	No			