

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	5378	OS Map	97	
Total length	0.7	Grid References	From	619 857
Length unsurfaced	0.6		To	619 850
		Location	Hawkin Hall	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/managment	
	Route with moderate use requiring some monitoring/managment	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	R & S France	Organization	TRF
Date	13/05/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	50%
	Crushed stone	50%	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Tractor ruts in grass section

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) Potential to be boggy/flood in wet weather

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations Hedged lane, mainly farm field access, potential to be overgrown at southern end	Signed from main highway	No	
	Signed both ends	No	
	Access from main Highway	- easy - awkward	No
	Route	- through - dead end	Yes
	Fords or water crossings		
	Gradient	- generally flat - generally undulating - has steep hills	Yes

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	10 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical		Maybe	Yes
	No			