

# Cumbria Countryside Access

## UCR and BOAT Survey Form

UCR Number and/or BOAT Number	3073	OS Map	86	
Total length	1.8	Grid References	From	553 460
Length unsurfaced	0.6		To	557 459
		Location	Walmersyke	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/management	
	Route with moderate use requiring some monitoring/management	
	Route with little or no use not likely to require monitoring/ management	<b>X</b>
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S Stout & L Dunn	Organization	TRF
Date	10/07/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	100%
	Crushed stone		Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.)      Edge of field grassland

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other)      None

Considerations for use and sensitivity re ecological issues, farming issues, other      Farmer has retained unploughed headland for track

General description of route, and observations  Field edge track, gated at both ends  Wrongly signposted "Footpath", and "No Vehicles" as farmer has had issues with people accessing water plant	Signed from main highway	*
	Signed both ends	
	Access from main Highway - easy	Yes
	Route - awkward	
	- through	Yes
	- dead end	
	Fords or water crossings	
Gradient - generally flat	Yes	
- generally undulating		
- has steep hills		

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	12 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Tramper use? ( motorized scooters for the disabled with off road capability)	Looks practical		Maybe	Yes
	No			