

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or BOAT Number	3119	OS Map	86	
Total length	0.71	Grid References	From	746 413
Length unsurfaced	0.3		To	749 412
		Location	Garrigill	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/managment	
	Route with moderate use requiring some monitoring/managment	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S Stout	Organization	TRF
Date	13/06/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac	50%	Grass	
	Crushed stone		Mud	
	Rocky	50%	Other	

Condition of surface (rutted, washed out, etc.) Rocky

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) Low concrete bridge which might flood in very wet weather

Considerations for use and sensitivity re ecological issues, farming issues, other None

General description of route, and observations Short, steep track with some loose stones – a good link link	Signed from main highway	Yes
	Signed both ends	Yes
	Access from main Highway	Yes
	Route	- easy - awkward - through - dead end
	Fords or water crossings	Yes
	Gradient	- generally flat - generally undulating - has steep hills
		Yes

Should normally be passable by	2 wheel drive		Quad	No
	4 wheel drive	No	Trail bike	Yes
	Carriage	No		
	Approx. width at narrowest	5 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical		Maybe
	No	No	