

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or	3173	OS Map	90	
BOAT Number	Part is 361001	Grid References	From	543 169
Total length	1.93		To	557 178
Length unsurfaced	1.93	Location	Rosgill	

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/managment	
	Route with moderate use requiring some monitoring/managment	
	Route with little or no use not likely to require monitoring/ management	Yes
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S. Stout	Organization	TRF
Date	13/06/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	
	Crushed stone	Yes	Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Generally good, with some puddles

Apparent sensitivity to winter/weather conditions
(river crossing, flooding, surface damage, other) None

Considerations for use and sensitivity re
ecological issues, farming issues, other None

General description of route, and observations Walled farm type lane, passing through quarry property and railway spur at one point Some gates	Signed from main highway	Yes
	Signed both ends	Yes
	Access from main - easy	Yes
	Highway - awkward	
	Route - through	Yes
	- dead end	
	Fords or water crossings	No
	Gradient - generally flat	Yes
- generally undulating		
- has steep hills		

Should normally be passable by	2 wheel drive		Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	12 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	No
	2 wheels	No

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe
	No		