

Cumbria Countryside Access

UCR and BOAT Survey Form

UCR Number and/or	3192	OS Map	90	
BOAT Number	311013	Grid References	From	558 289
Total length	1.34		To	559 299
Length unsurfaced	1.34	Location		

CCC Classification (Tick recommendation)	Route with significant use requiring significant monitoring/managment	
	Route with moderate use requiring some monitoring/managment	
	Route with little or no use not likely to require monitoring/ management	X
	Unsuitable route, should not be on MPV sustainable access map	

LDNPA classification if applicable, criteria as above, but green becomes light green for dead ends

Surveyor	S Stout	Organization	TRF
Date	13/06/16	or interest	

Surface (note % of each type of surface, Describe "other")	Tarmac		Grass	100%
	Crushed stone		Mud	
	Rocky		Other	

Condition of surface (rutted, washed out, etc.) Good surface with slight rutting

Apparent sensitivity to winter/weather conditions (river crossing, flooding, surface damage, other) None at present level of usage

Considerations for use and sensitivity re ecological issues, farming issues, other Take care of stock

General description of route, and observations Hard surface covered with grass, passing through fields Wrongly signed Footpath from points where Footpaths 311008 & 9 meet it Interest is historic as it accesses St Ninian's Church, Brougham	Signed from main highway	Yes
	Signed both ends	
	Access from main - easy	Yes
	Highway - awkward	
	Route - through	
	- dead end	X
	Fords or water crossings	
Gradient - generally flat		
- generally undulating	Yes	
- has steep hills		

Should normally be passable by	2 wheel drive	Yes	Quad	Yes
	4 wheel drive	Yes	Trail bike	Yes
	Carriage	Yes		
	Approx. width at narrowest	12 ft		

Recommend one way use due to steepness, narrowness, other condition, state reason	4 wheels	
	2 wheels	

Worth evaluating for Tramper use? (motorized scooters for the disabled with off road capability)	Looks practical	Yes	Maybe
	No		